



# Flight Test Assessments of Pilot Workload, System Usability, and Situation Awareness of TASAR




Kelly A. Burke, PhD
Human Factors Principal Investigator
NASA Langley Research Center
kelly.a.burke@nasa.gov



# Traffic Aware Strategic Aircrew Requests



Cockpit automation and connectivity to real-time operational data are leveraged to enhance route-change procedures for flight optimization





# Traffic Aware Planner (TAP) and the Emerging "Connected Aircraft"



## Designed as an Electronic Flight Bag (EFB) application

Ownship data via standard avionics interfaces (read only)
Aircraft current state, active route, traffic data

Environment data via air/ground connectivity Latest winds, weather, airspace status, etc.



### Two Modes of Operation


#### **Auto Mode**

Computes real-time route optimizations



#### Manual Mode

Analyzes pilot-entered route changes






# Human Factors Challenge



Flying an aircraft involves a complex, multidimensional series of behaviors, only some of which can be observed directly



- Cockpit procedures, technology, and instrumentation continue to change and become more complex
- New technologies require evaluation of the potential impact on pilot workload and situation awareness
- One method is the use of subjective assessments of workload and situation awareness



# Flight Test Objectives



- Conduct a human factors evaluation of the TAP software application and interface
- Investigate interaction with TAP Human Machine Interface (HMI) during normal flight operations
- Assess effects on perceived workload and situation awareness
- Assess system usability, comprehensibility, and usefulness



# TASAR Flight Tests in the National Airspace System



#### Nov 2013, June 2015













# Methodology



#### **Data Collection**

- Two evaluation pilots per flight (cockpit and cabin)
  - 12 flights
  - 2 to 2.5 hours per flight
- Subjective measures administered
  - In flight
  - Post flight

#### **Subjective Measures**


- Bedford Workload Scale. The Bedford Workload Scale is a uni-dimensional rating scale designed to identify operator's spare mental capacity while completing a task.
- System Usability Scale (SUS). The SUS provides a quickly administered and reliable tool for measuring subjective assessments of usability.
- Situation Awareness Rating Technique (SART). The SART is a subjective measure of situation awareness that can provide an index of how well operators are able to acquire and integrate information in a complex environment.
- Post-Flight TAP HMI Evaluation. This questionnaire consisted of five-point Likert-type rating scales regarding the overall comprehensibility, usability, and usefulness of the TAP HMI as well as questions about specific display features.






#### **Bedford Workload Scale**

- Evaluation Pilots reported their cognitive workload as low (M = 2.64, SD = 0.84)
  - Rating of 1 indicating insignificant workload and a rating of 10 indicating a very high level of workload and task abandonment










## System Usability Scale

- No significant differences based on pilot position (cockpit vs. cabin)
- SUS calculated scores were collapsed across pilot position
- Pilots reported ratings of high perceived usability (M = 80.0, SD = 14.33)

# Distribution of SUS Calculated Scores Collapsed Across Pilot Position








## Situation Awareness Rating Technique

- No significant differences based on pilot position (cockpit vs. cabin)
- SART calculated scores were collapsed across pilot position
- Pilots reported mid-range situation awareness scores (M = 7.93, SD = 2.95)
  - Indicates that situation awareness in the cockpit was not affected, either positively or negatively, by interacting with the TAP HMI

# Distribution of SART Calculated Scores Collapsed Across Pilot Position








#### **TAP HMI Evaluation**

- Startup Checklist and Auto Mode Screens comprehension was either "Easy" (2) or "Very Easy" (1)
  - -M = 4.43, 4.79; SD = 0.76, 0.43
- Manual Mode Screen slightly less comprehensible, with 43% of pilots reporting that comprehension was "Somewhat Easy" (3)
  - -M = 3.86, SD = 0.86
- All three display screens were found to be either
  - "Useful" or "Very Useful" and
  - "Usable" or "Very Usable"

#### **Overall HMI Evaluation Ratings - TAP Display Screens**





## **Conclusions**



- Interaction with the TAP HMI did not create a significant level of additional workload and generally did not inhibit successful completion of tasks
- TAP HMI has a high degree of comprehensibility, usefulness, and usability
- Pilot situation awareness, as rated in flight, was not affected either positively or negatively by interacting with the TAP HMI
  - However, when asked post-flight, the pilots indicated that TAP enhanced their situation awareness
- Results are being used to further refine and improve the capabilities and features of the TAP HMI in preparation for operational trials with partner airlines planned for 2017-2018



# Questions?



